
Data current as of: 25-11-2026 16:19

Link to the product: https://www.tesam.eu/m41638-abs-sensor-reamer-set-8-pcs-p-13629.html



M41638 - ABS sensor reamer set, 8 pcs

Price with TAX	**1 525.35 zł**
Price	**1 240.12 zł**
Availability	**Na zamówienie - 21 dni**
Shipping time	**21 days**
Number	**H.41638**

Product description

Product information "ABS sensor reamer set, 8 pieces"

- for possibly drilling out a defective ABS sensor
- for cleaning the various guide holes of the ABS sensors
- Optimum, custom-fit work made possible by the fine-toothed joint ratchet

Contents:
1 x reamer 11 x 84 [mm] (also available individually item no. 41639)
VW: Golf VI + Cabrio + Variant, Beetle from 2011, Golf V + Plus + Variant, Jetta III + IV, Passat (Mod.C3), CL + Variant, Scirocco from 2009, Sharan from 2010, Tiguan(Mod.5N), Touran from year 2005
and other identical models from:
AUDI: A3 (Mod.8P), Q3 (Mod.8U), TT (Mod.8J),
SEAT: Altea + XL, Leon, Toledo III,
ŠKODA: Oktavia (Mod.1Z), Superb (Mod.3T), Yeti from model year 2010

1 x reamer 10 x 150 [mm]
VW Golf 5, Polo 9N, T5, Skoda Fabia, Seat Ibiza, Opel Insignia

1 x reamer 15 x 23 [mm]
Mercedes A Class, Mazda, Ford

1 x Reamer 14 x 32mm
BMW E38, E39, E52, E60, E61, E63, E64, E65, E66, E70, E71

1 x reamer 18 x 23 [mm]
Audi, VW, BMW E36, E46, Seat, Skoda

1 x reamer 18 x 34 [mm]
Audi, VW, Seat, Skoda, commercial vehicles

1 x twist drill 10 x 133 [mm]
for drilling out corroded sensors

1 x articulated ratchet
for hard-to-reach places