Data current as of: 06-11-2026 07:34

Link to the product:
https://www.tesam.eu/s0001582-replacement-m38301-1-tool-for-replacing-the-alternator-belt-without-tensioner-poly-v-belt-poly-v-belt-p-12211.html



S0001582 => replacement M38301-1 - tool for replacing the alternator belt without tensioner / Poly V-belt / Poly V-belt

Price with TAX	**975.15 zł**
Price	**792.80 zł**
Availability	**Dostępny - 24h**
Shipping time	**24 hours**
Number	**S0001582**
EAN code	**5904966408045**

Product description

Ensures installation of flexible multi-ribbed belts without the risk of damaging them.

Application:
Cars
- BMW: 118, 120, 318, 320, 325, 330, 335, 520, 525, 530, 535, 635, 720, X3, X5
- Audi: A3 1.6 / 2.0 D
- Seat: Altea, Ibiza 1,6 / 2,0 D
- Skoda: Octavia, Yeti 1.6; 2.0 D
- Volkswagen VW: EOS, Golf, Passat, Polo, Sorocco 2.0 D
- Chrysler: Grand Voyager, Voyager 2.5 D / 2.8 D
- Ford: C-Max, Mondeo, Tourneo, Transit 1,4 / 1.6 / 1.8 / 2.0; Ttransit Tourneo 2.2 D Courier, Fiesta, Fusion 1.6
- Mazda: 3/5, Axela 1,8 / 2.0 model 2 1,2 / 1.4 / 1.6
- Mercedes: Sprinter, Viano, Vito 3.0 D
- Peugeot: 206, 207, 307, Boxer 1.6 D / 2.2 D / 3.0 D
- Citroen: C2, C3, C4, Jumper, Relay 1.6 D / 2,2 D / 3,0 D
- Fiat: Albea, Doblo, Ducato, Fiornino Qubo, Linea, Palio, Siena, Stilo, Strada Pickup 2.2 D / 2.3 D / 3.0 D, Doblo, Marea, Multipla 1.6
- Iveco: Daily 2.3 D / 3.0 D
- Volvo: C30, S40, V50 1.6 / 1.8 / 2.0
- Lancia: Lybra 1.6
- Mitsubishi: ASX 1.8 D