

Data current as of: 24-07-2025 01:44

Link to the product:

<https://www.tesam.eu/s0003192-setting-device-for-determining-the-direction-of-reaming-the-broken-injector-mounting-screw-with-30-hpi-control-pilots-p-13684.html>



S0003192 - Setting device for determining the direction of reaming the broken injector mounting screw with 3.0 HPI control pilots

Price with TAX	525.35 zł
Price	427.11 zł
Availability	Dostępny - 24h
Shipping time	24 hours
Number	S0003192

Product description

The device provides the correct, permanent direction for reaming the broken injector mounting screw

Application:

Cars with 3.0 HPI engines - EURO 5

- Fiat Ducato
- Citroen Jumper
- Peugeot Boxer
- Iveco

The device does not fit 3.0 HPI engines (EURO 4)