

Link to the product:

<https://www.tesam.eu/s0003192-setting-device-for-determining-the-direction-of-reaming-the-broken-injector-mounting-screw-with-30-hpi-control-pilots-p-13684.html>



S0003192 - Setting device for determining the direction of reaming the broken injector mounting screw with 3.0 HPI control pilots

| | |
|----------------|-----------------------|
| Price with TAX | 525.35 zł |
| Price | 427.11 zł |
| Availability | Dostępny - 24h |
| Shipping time | 24 hours |
| Number | S0003192 |

Product description

The device provides the correct, permanent direction for reaming the broken injector mounting screw

Application:

Cars with 3.0 HPI engines - EURO 5

- Fiat Ducato
- Citroen Jumper
- Peugeot Boxer
- Iveco

The device does not fit 3.0 HPI engines (EURO 4)