

Link to the product: <https://www.tesam.eu/m6801-05-12-impact-socket-torx-t100-x-78-mm-with-hole-p-13300.html>



## M6801-05 - 1/2" impact socket Torx T100 x 78 mm with hole

Price with TAX	<b>107.75 zł</b>
Price	<b>87.60 zł</b>
Availability	<b>Na zamówienie - 48h</b>
Shipping time	<b>48 hours</b>
Number	<b>C.6801-05</b>
EAN code	<b>4037374024499</b>

### Product description

- chrome molybdenum steel,
- with an O-ring groove and a hole for protection,
- forged from one piece of steel,
- for the screw connection of the central valve of the camshaft adjustment when changing the timing chain or repairing the engine,

- for Mercedes class cars:
  - A (W176), AMG GT (C190),
  - AMG GT Roadster (R190),
  - B (W246, W242),
  - C (W204, W205), CLA Coupe (C117), CLA Shooting Brake (X117), CLS (C218, C257),
  - E (W212, W213), E Cabriolet (A207, A238), E Coupe (C207, C238),
  - G (W463), GLA (X156), GLC (X253), GLE (W166), GLE Coupe (C292), GLK (X204), GL (X166),
  - M (W166),
  - R (W251, V251),
  - S (W221, W222, V222, X222), S Cabriolet (A217), S Coupe (C216, C217), SL (R231) and SLK (R172)

- engine codes:
  - M133, M157, M176, M177, M178, M256, M264, M270, M271.8, M274, M276, M278,

- service tool number:
  - 271589001000/177589000900,