

Link to the product: <https://www.tesam.eu/m6801-05-12-impact-socket-torx-t100-x-78-mm-with-hole-p-13300.html>



M6801-05 - 1/2" impact socket Torx T100 x 78 mm with hole

Price with TAX	107.75 zł
Price	87.60 zł
Availability	Na zamówienie - 48h
Shipping time	48 hours
Number	C.6801-05
EAN code	4037374024499

Product description

- chrome molybdenum steel,
 - with an O-ring groove and a hole for protection,
 - forged from one piece of steel,
 - for the screw connection of the central valve of the camshaft adjustment when changing the timing chain or repairing the engine,
- for Mercedes class cars:
 - A (W176), AMG GT (C190),
 - AMG GT Roadster (R190),
 - B (W246, W242),
 - C (W204, W205), CLA Coupe (C117), CLA Shooting Brake (X117), CLS (C218, C257),
 - E (W212, W213), E Cabriolet (A207, A238), E Coupe (C207, C238),
 - G (W463), GLA (X156), GLC (X253), GLE (W166), GLE Coupe (C292), GLK (X204), GL (X166),
 - M (W166),
 - R (W251, V251),
 - S (W221, W222, V222, X222), S Cabriolet (A217), S Coupe (C216, C217), SL (R231) and SLK (R172)
 - engine codes:
 - M133, M157, M176, M177, M178, M256, M264, M270, M271.8, M274, M276, M278,
 - service tool number:
 - 271589001000/177589000900,