

Link to the product: <https://www.tesam.eu/mh43813-replacement-s0000820-mitsubishi-cam-locks-p-8149.html>



## MH43813 -> Replacement S0000820 - Mitsubishi cam locks

Price with TAX	<b>278.10 zł</b>
Price	<b>226.10 zł</b>
Availability	<b>Dostępny - 24h</b>
Shipping time	<b>24 hours</b>
Number	<b>H.43813</b>
EAN code	<b>5904157460791</b>

### Product description

To lock the gears in Mitsubishi Nr. MD Hyundai No. 998738. 0924-28000 pulley, Mitsubishi MD No. 998767, No. 0924-28100 Hyundai Hyundai: 1.6i - 1.8 - 2.0 - 2.4, Proton: 1.8, Mitsubishi: 1.6 - 1.8 16V - 1.8 GDi - 2.0 16V - 2.0 GDi - 2.4 - GDI 2.4 - 2.5 6V - 6V 3.0 - 3.5 6V