

Link to the product: <https://www.tesam.eu/s0000748-kit-for-removing-a-broken-filament-from-a-glow-plug-m8-x-1-p-9285.html>



S0000748 - Kit for removing a broken filament from a glow plug M8 x 1

Price with TAX	622.33 zł
Price	505.96 zł
Availability	Dostępny - 24h
Shipping time	24 hours
Number	S0000748
EAN code	5904966404733

Product description

The kit includes:

- Hammer
- Drill the broken filament candle
- Tap to a broken filament candle
- Adapter to pull the broken filament glow plug
- Guide adapters in the glow plug socket M8 x 1

Application:

- Mercedes E Class 211 W, S Class, Sprinter, Vito after 2005 engines
- OM 642 V6 capacity 2.2 / 3.0 / 3.2
 - OM 651 after 2009 220 CDI, 200 CDI