

Link to the product:

<https://www.tesam.eu/s0000750-max-set-for-removing-a-broken-filament-of-a-glow-plug-m10x1mm-m10x125mm-hdi-m8x1mm-m9x1-toyota-d4d-m10x125mm-and-others-p-9289.html>



## S0000750 - MAX set for removing a broken filament of a glow plug M10x1mm, M10x1.25mm, HDI M8x1mm, M9x1, Toyota D4D M10x1.25mm and others

Price with TAX	<b>2 322.35 zł</b>
Price	<b>1 888.09 zł</b>
Availability	<b>Dostępny - 24h</b>
Shipping time	<b>24 hours</b>
Number	<b>S0000750</b>
EAN code	<b>5904966404764</b>

### Product description

Set contains:

- hammer
- drill for a broken candle filament M10
- M10 broken filament tap
- adapters for removing a broken glow plug filament
- guide of adapters in the glow plug socket M10 x 1.00 mm
- adapter guide in the glow plug socket M10 x 1.25 mm - drill for a broken candle filament M8 x 1 mm
- a tap for a broken candle filament M8 x 1 mm
- adapter guide in the glow plug socket M8 x 1 mm
- drill bit for broken candle filament M9 x1 mm
- a tap for a broken candle filament M9 x 1 mm
- adapter guide in the glow plug socket M9 x 1 mm

Application:

Cars:

CDI

1.6 HDI Peugeot, Citroen, Mazda, Ford, Fiat, Volvo, Mini,

Toyota D4D

Fiat 1.3 Multi Jet, Fiat Ducat 2.3 / 3.0 Fiat Grande Punto M9 x 1 mm

Mercedes E Klasa 211 W, S Klasa, Sprinter, Vito after 2005

Motors

- OM 642 V6, capacity 2.2 / 3.0 / 3.2

- OM 651 after 2009 220 CDI, 200 CDI