

Link to the product: <https://www.tesam.eu/s0001414-tools-for-removing-a-broken-injector-p-12044.html>



S0001414 - Tools for removing a broken injector

| | |
|----------------|-----------------------|
| Price with TAX | 3 471.07 zł |
| Price | 2 822.01 zł |
| Availability | Dostępny - 24h |
| Shipping time | 24 hours |
| Number | S0001414 |
| EAN code | 5904966407208 |

Product description

Elements of the set:

- 1) S0000896 - HDI hydraulic injector puller bolt - M15 x 0.5
- 2) S0000392 - M17 x 0.75 - Opel Vivaro 2.0 hydraulic injector puller bolt
- 3) S0000904 - Screw for removing the injected M14 x 1.5 mm injector - reinforced hydraulic system
- 4) S0001045 - Specialist M15 x 0.5 mm thread, long 180 mm
- 5) S0000448 - Screw for extracting a broken M16 x 1.5 mm injector
- 6) S0000891 - Specialist M14 x 1.5 tap, 175 mm long
- 7) S0000800 - Specialist M17 x 0.75 mm thread, 180 mm long
- 8) S0001369 - Specialist M20 x 1.00 mm tap
- 9) S0001105 - Adapter for extracting injector barrel 2.0 CDTI / 2.2 TDCI, HDI, JTD
- 10) S0001400 - M16 x 1.5 mm tap for threading a broken injector with an extended tap guider
- 11) S0001153 - Cobalt drill bit 12 mm (151 mm)
- 12) S0001152 - Cobalt drill bit 14 mm (160 mm)
- 13) S0001155 - 19 mm cobalt bit (198 mm)